

What do LAUNDRY SYMBOLS mean

PROFESSIONAL CLEANING (dry cleaning)



Professional cleaning
symbol



Dry clean
HCS only



Gentle cleaning with
hydrocarbon solvents



Very gentle cleaning
with hydrocarbon
solvents



Dry clean,
(PCE) only



Gentle cleaning with PCE



Very gentle cleaning
with PCE



Professional
wet clean



Do not dry clean



Do not wet clean

WASHING



Machine wash



Wash at or below
80°F or 30°C



Wash at or below
105°F or 40°C



Wash at or below
120°F or 50°C



Wash at or below
140°F or 60°C



Wash at or below
160°F or 70°C



Wash at or below
200°F or 95°C



Hand wash



Do not wash



Do not wring

BLEACHING



Bleaching



Bleaching with chlorine
allowed



Non-chlorine bleach
when needed



Do not bleach



Do not bleach

DRYING



Tumble drying



Tumble drying (low
temperature)



Tumble drying (normal)



Tumble drying (high
temperature)



Do not tumble dry



Drying symbol



Line dry



Dry flat



Drip dry



Dry in the shade



Line dry in the shade



Dry flat in shade



Drip dry in shade

IRONING



Ironing symbol



Iron at low temperature



Iron at medium
temperature



Iron at high temperature



Do not iron